

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation


Campus Location and Description: Deer Creek Elementary

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

Remove old switch
Finish APs

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature


Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation


Campus Location and Description: Dallas Park Elementary

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

<u>Cable Mgmt</u>
<u>Remove old chassis</u>
<u>Finish AP installs</u>

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.



Customer Signature

6/18/15

Date

Customer Acceptance of Work Completion

Crowley ISD - Huawei and Aruba Network Implementation


Campus Location and Description: North Crowley Ninth Grade Ctr

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

<u>CABLE MGMT / DRESSING</u>
<u>Remove old chassis & deliver to Admin Bldg</u>

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

06-15-14

Date

Customer Acceptance of Work Completion

Crowley ISD - Huawei and Aruba Network Implementation


Campus Location and Description: Crowley 9th Grade Center

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

EXTRA APs in Closet
Cable MGMT / Remove old chassis

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

06-15-16
Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation


Campus Location and Description: Crowley HS

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

COBLE MGMT
Remove old switches

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

4/15/14
Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation


Campus Location and Description: Best Race Elementary

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

<u>Remove old chassis</u>

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

6-18-16
Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation

Campus Location and Description:

North Crowley HS

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

<u>Remove old chassis and cable mgmt</u>

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

6/15/16
Date

Customer Acceptance of Work Completion

Crowley ISD -- Huawei and Aruba Network Implementation

Campus Location and Description: Oakmont ES

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

<i>APs need to be finished</i>
<i>Remove & deliver old chassis</i>

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

6/15/16
Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation

Campus Location and Description: Meadowcreek ES

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed


Please note any exceptions or outstanding tasks or issues:

Finish AP install
Remove old chassis

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.



Customer Signature



Date

Customer Acceptance of Work Completion

Crowley ISD - Huawei and Aruba Network Implementation


Campus Location and Description: Jackie Carden ES

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

<u>Remove old chassis</u>

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

4/15/16
Date

Customer Acceptance of Work Completion

Crowley ISD -- Huawei and Aruba Network Implementation

Campus Location and Description: Hargrave Elementary

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

Complete APs
Remove old Chassis

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

4/11/16
Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation


Campus Location and Description: CROWLEY M.S.

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

Finish APs
Cable MGMT

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

4/15/14
Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation


Campus Location and Description: Sydney Pointer

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

<u>Cable MGMT</u>
<u>Remove old chassis</u>

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

6/10/16
Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation


Campus Location and Description: Bill R Johnson

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

Remove old chassis
Cable Mgmt

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

6/10/14
Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation


Campus Location and Description: Parkway Elementary

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

Old Chassis
Cable Mgmt

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

5/15/14
Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation

Campus Location and Description: CLC

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

Old Cables Removed
Cable MGMT

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

6/15/16
Date

Customer Acceptance of Work Completion


Crowley ISD – Huawei and Aruba Network Implementation

Campus Location and Description: Sewell AG

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

6/18/16
Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation


Campus Location and Description: She Crutch

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

CABLE MGMT
Remove old switch

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

6/15/16
Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation


Campus Location and Description: David Walker Inter

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

<u>Remove old chassis</u>
<u>Finish AP install</u>
<u>Cable MGMT</u>

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

6/15/14
Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation


Campus Location and Description: HF STEPHENS

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

Remove old switch
Cable Dressing

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

4/10/16
Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation

Campus Location and Description: Many Halls Inter

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

CABLE MGMT
Remove old chassis

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

6/15/16
Date

Customer Acceptance of Work Completion

Crowley ISD -- Huawei and Aruba Network Implementation


Campus Location and Description: SYCAMORE

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

Remove old chassis
Cable Mgmt

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

9/15/14
Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation


Campus Location and Description: SH Crowley Inter

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

Remove old chassis
Cable MGMT

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

4/10/16
Date

Customer Acceptance of Work Completion

Crowley ISD – Huawei and Aruba Network Implementation


Campus Location and Description: Summer Creek M.S.

- All hardware has been delivered according to BOM
- All switches have been racked according to design
- All cables are dressed according to customer instructions
- All switch indicator lights are free of error
- All connectivity has been tested and confirmed in working condition
- Closets are clean and free of trash
- Old equipment has been removed and delivered to customer specified location
- If applicable, UPS has been installed

Please note any exceptions or outstanding tasks or issues:

Remove old chassis
Cable Mgmt
Finish AP install

By signing below I agree that the specified work is complete according to the BOM and Design specifications. All hardware has been delivered and accounted/signed for.


Customer Signature

9/18/14
Date